

# **Network Video Recorder**

Version: V4.21.008 build190625

### **Release Note**

(2019-7-17 Internal)

	Firmware Version:	V4.21.008 build190625
	SDK Version:	V6. 0. 2. 30_bui1d20190325
Firmware	Play Library:	V7. 3. 7. 32_Build20190305
Basic	Web component:	V4.0.1 build190625
Information	IVMS-4200:	V2. 6. 18. 8 build20190520
	OpenSDK Version:	V1.5.55.1 build 181101

# **Reason of Upgrade**


Add new features and optimize product performance.



#### New features

#### 1. **(Repair database on Web Client)**

Add two ways to repair database on the Web client: repair video and repair all the data. Repairing video takes less time, about half an hour. Repairing all data will repair videos, pictures and events. It takes a long time, depending on the size and number of HDD, and usually takes several hours.



- During the repair process, the normal storage of videos, events and pictures will not be affected.
- 3) Record the start log at the beginning of the repair and the end log at the end. The log is Operation -- HDD Detect.

## **Modified functions**

### 1. [Stability Optimization]

Solve some known issues and enhance product stability.

#### Related product list:



I series NVR	DS-9600NI-I16, DS-9600NI-I8	
	DS-8600NI-I8	
	DS-7700NI-I4(/P), DS-7732NI-I4/24P, DS-7700NI-I4(B)(/P)	
	DS-7600NI-I2(/P)	

#### <u>Customer Impact and Recommended Action</u>

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

#### Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.