

Network Access Controller DS-K2600 Series

V2.0.4_build180706 Release Notes

| | | |
|--|------------------|---------------------------------------|
| Device Model: DS-K2601 DS-K2602 DS-K2604 | Firmware Version | V2.0.4_build180913 |
| | SDK Version | HCNetSDKV5.3.1.35_build20170911_win32 |
| | EHome Version | EhomeSDK_V1.2.0.7_build20170712 |
| | 4200 Version | V2.7.2.4 build20180806 |

Reason of Upgrade

Add or modify functions, fix bugs, enhance products quality and meet customers' requirements.

Bugs Fix

1. Fix a bug when multiple authentication time out, door can still open by input card password.
2. Fix a bug that multiple authentication function can not work with card and password authentication mode.
3. Fix a bug that device will crash when try to open remote configuration menu.

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.

Hikvision Digital Technology CO., Ltd.
No. 555 Qianmo Road, Binjiang District, Hangzhou 310052,
China
Tel: +86-571-8807-5998
FAX: +86-571-8993-5635
Email: support@hikvision.com